Vinyl and Faux Leather Fabrics

teal

Manufacturer:

SPRADLING®

Spradling®

Fabric Range:

MARDI GRAS

Description:

The Mardi Gras range of colourful, phthalate-free and antimicrobial contract coated fabrics from Spradling UK combines style, safety and quality at an affordable price. Mardi Gras is flame retardant to CRIB 5 and complies with all othe relevant requirements for contract use.It is suitable for heavy domestic and contract upholstery, as well as for a wide range of commercial seating and healthcare furniture applications.
Antimicrobial, Phthalate FREE, Flame Retardant

Design Style:

Colour Selections:



MDG-4001 SNOW

MDG-4002 CREAM

MDG-4021 GOBI

MDG-4013 MOCHA

MDG-4019 TANGERINE

MDG-4020 CRIMSON

MDG-4024 MONROE

MDG-4017 FUCHSIA

MDG-4012 PACIFIC

MDG-4011 BLUE SKY

MDG-4008 LAVANDER

MDG-4009 DAMSON

MDG-4025 SMOKE

MDG-4022 DOLPHIN

MDG-4023 NAVY

MDG-4014 CHARCOAL

MDG-4004 AVOCADO

MDG-.4006 AQUA

MDG-4007 FOREST

Technical Details Input

teal

Composition:

Topcoat:Vinyl Topcoat/ Backing:100% Cotton

FR Certification: :

EU: EN 1021 Part 1 & 2 FR: NF P 92-503/M2 UK: BS 5852 Part 2 CRIB 5

Fabric care and maintenance:

PRODUCTS WITH PERMABLOK3®, & PERMAGUARD®
Spradling® products are in its majority protected by PERMABLOK3® or PERMAGUARD®, two of the most effective defence systems against germs, stains and abrasion.Two impermeable barriers to safeguard your investment. For optimum care and cleaning please read the following instructions and recommendations.

Disinfectant Use:
The information published in this care guide refers to the performance of PERMABLOK3® and PERMAGUARD® products in specifics tests conducted under laboratory conditions. Results may vary under actual conditions.

Asepticare TB + II
Antifect (in 0.5 % dilution) Caviwipes XL Packed Cleanisept Wipes
Clorox Healthcare Bleach Germicidal Wipes Coverage Plus
Germicidal Wipes Desomed rapid
FD 366
Hydrogen Peroxide Cleaner Disinfectant Wipes Instrunet Anionsurf
Lysol Foaming Disinfectant Cleaner
Microzid
Oxivir TB Wipes
Oxycide Diluted –3oz/gl in water PDI Sani-cloth bleach wipes Sanicloth AF 3
Sodium Hypochlorite. Disinfectant
Bletach cleaner. Dilution: 1:10 mix of bleach and water.
Surfanios Premium
(in 0,25% dilution)
Surfa'Safe Premium
(in 0,25% dilution)
Super Sani-cloth
Virex II 256 (1:256 Dilution) Virox 5 Rtu
Wet wipe
Wex Cide 128 (1:128 dilution)

Spradling® Europe is not sponsored by, affiliated with, or endorsed by the above trademark owners. Additionally, any use by Spradling® Europe of any third-party trademark does not constitute any endorsement by Spradling® Europe of such third parties.
Rinse the area with clean water, then dry with a clean, lint-free cloth after using any disinfectants and cleaners.

Cleaning After Disinfection:
The coated fabric should be cleaned periodically in order to maintain its appearance and prevent build-up of dirt and contaminants. Any stain, spills, or soiling should be cleaned up immediately to prevent the possibility of permanent staining.
Use a mixture of liquid soap (neutral pH) and water or our approved
cleaning products for coated fabrics to remove stains on the surface of the material. Remove only with a damp white cloth. Lacquers, strong cleaners, detergents, xylene-based solutions, acetone, or ketone (MEK) cause immediate damage and contribute to the deterioration of the material. The use of such cleaners is at the owner’s risk.

Daily Cleaning
1. Clean the entire surface using a mixture of 1:9 liquid soap (neutral pH) and water. Do not use soap or cleaning solutions that contain alcohol, ketones, xylene, acetates or solvents (mineral/white spirits).
2. Completely remove excess cleaner with a white, clean, damp cloth.
3. Dry the surface.
Cleaning methods to removetougher stains
Step 1: Coffee, juice, red wine, sauces, chocolate, grease, crayon and suntan lotion. Remove excess spill with a damp cloth. Clean with a 1:9 mix of neutral liquid soap and water. Next, rinse with clean water and d r y.
Step 2: Make-up Use a straight application of neutral PH soap.Wipe with a clean white cloth or soft brush, rinse with clean water, and dry.
Step 3: Blood, urine, faeces and all other tough stains Use a 1:10 mix of Isopropyl alcohol and water. Rinse thoroughly with clean water and d r y.
Note: For cleaning use a soft white cotton cloth saturated with the recommended cleaning agent and rub the stain in circles 10 times. Pat dry with another soft white cotton cloth and check the results. Do not use steel bristle brushes, abrasive scouring pads or metal, these cause permanent damage to the fabric. Methods 2 & 3 are not recommended for everyday cleaning!
After cleaning, rinse the area with clean water, then dry with a clean, lint-free cloth. Failure to remove chemical residue will cause discolo- ration of the coated fabric surface to manifest earlier in the life cycle of the product.